

Inspection Report

Name of Work : Maintenance of BBMP Drilled Borewell in Ward No. 09 (Vidyaranyaपुरa), Vidyarnyapura Sub Division.
Work Order : EE/BTP/BBMP/E-PMT/07(16464)/WO/294/2014-15
Dated: 05.02.2015
Agency : Bharath Adithya. V
B.R. No & Date : 286/2015-16 Dated: 31.03.2016
Bill Amount : 10,37,180.00
Job Code : 009-15-000031
P. Code : P-1802
Date of Inspection : 11-04 - 2016.


The above said work "Maintenance of BBMP Drilled Bore well in Ward No 09 (Vidyaranyaपुरa) Vidyarnyapura Sub on way shown to one Engineer concerned Ward Engineer.

The above said work is inspected by me along with concerned ward Engineer and verified secondly.

The work done is Satisfactory



MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು,
ವಿದ್ಯಾರಣ್ಯಪುರ ಉಪ ವಿಭಾಗ,
ಯಲಹಂಕ ಪರಮ,
ಬಿ. ಬೆಂ. ಮ. ಪಾ., ಬೆಂಗಳೂರು-97.